

RYDEEN

Technical Bulletin

Rydeen Mobile Electronics
2701 Plaza Del Amo, Suite 705
Torrance, CA 90503

Bulletin #

6062016

Concerning Product and/or Application:

Single source input monitors

Date:

6/06/2016

Subject: Integrating Side and Rear cameras into single input monitor

Symptom: Having only one switching input on double-din or monitor

Cause: Manufacture only accepts one video input (Backup Camera)

Corrective Action: Adding Switcher for both cameras into one source

Instructions: Add switcher at monitors input;

Video Out (RCA): Monitors input
Video 2 (RCA): Rear Camera
Video 3 (RCA): Side Camera(s)
Black Wire: Chassis Ground
Red Wire: Monitor Trigger
White/Red Wire: Red Anode Wire (Reverse trigger)
White/Blue Wire: Blue Anode Wire (Side Cam trigger output)

Video 1 is not used

Instructions:

